

Field Inspection Report

Inspected By: PLA15708 Inspection Date: 11/14/2010

Asset Number: 102260202

Property Address: 45291 PENTWATER DR

Macomb, MI 48044

Comments

Property type: Single Family

Occupancy Type: Occupied

Property Secured: No

Yard sign: No

No Trespassing Sign: No

Lockbox Installed: No Lockbox Code:

Electric On: No

Water On: No

Gas On: No

Property Weathertight: No

Any posted citations?: No

Any safety hazards?: No

Pool clean and operating?: N/A

Pool Secure?: N/A

INTERIOR/EXTERIOR

Sales Clean needed?: No

Trashout needed?: No

Yard Startup needed?: No

Property winterized and posted?: No

Any missing appliances?: No

Unfinished? % complete?: No

Estimated cost to complete?: N/A

Damage present?: No

Is damage extensive?: No

Type of damage?: N/A

Location of Damage?:

Moisture/Discoloration present?: No

Moisture/Discoloration

Comments:

11/18/2010 9:25:26 AM Page 1 of 2

Field Inspection Report



INSPECTION COMMENTS

Car in drive, things inside.







11/18/2010 9:25:26 AM Page 2 of 2